20

NJ0083459

United States Environmental Protection Agency (EPA)
Region 2
290 Broadway
New York, NY 10007-1866

Underground Storage Tank (UST) Inspection Form

INSPECTOR NAME(S): JEFF BLAIR **DATE:** 05/19/15

SIC CODE: **ICIS #:**

I. Location of Tank(s) ☐ Tribal

Facility Name: SITE # 32084
Street Address: MCLEAN BLVD + 33RD STREET
City: PATERSON State: NY Zip Code: 07514
County: PASSAIC
Phone Number: (973) 341-6999 Fax Number:
Contact Person(s): EDGAR AMADOR, ENV. COMP. SPECIALIST

II. Ownership of Tank(s) ☐ same as location (I.)

Owner Name: NJ ENERGY CORP.
Street Address: 536 MAIN STREET
City: NEW PALTZ State: NY Zip Code: 12561
County:
Phone Number: (845) 256-0162 Fax Number:
Contact Person(s): SCOTT PARKER, DIRECTOR OF

IIA. Ownership of Other Facilities

☐Do you own other UST Facilities (Yes) / No

If Yes, How many Facilities 210 How many USTs 695

III. Notification

☐ Notification to implementing agency; name NJ DEP (EFFECTIVE THROUGH 03/31/17)
State Facility ID # NJ 0083459

IV. Financial Responsibility TOKIO MARINE SPECIALTY INS. CO. (EXPIRES 03/31/16)

☐ State Fund ☐ Private Insurance: Insurer/Policy # PHPK 1477490
☐ Guarantee ☐ Surety Bond ☐ Letter of Credit
☐ Local Government ☐ Self Insured ☐ **Not Required** (Federal & State government, hazardous substance USTs)

V. Release History N/A ☑

☐ To your knowledge, are there any public or private Drinking Water Wells in the vicinity ? **Yes / (No)**

☐ Evidence of release or spills at facility ☐ Greater than 25 gallons (estimate)
☐ **Releases reported to implementing agency; if so, date(s)** _____ [280.53]
☐ Release confirmed; when and how _____
☐ Initial abatement measures and site characterization ☐ Free product removal
☐ Soil or ground water contamination ☐ Corrective action plan submitted
☐ Remediation ongoing ☐ Remediation completed, no further action; date(s)_____

Notes: ✓

NJ 0088458

VI. Tank Information Tank No.	1ES	1EG				
Tank presently in use	YES →					
If not, date last used (see Section XII)						
If empty, verify 1" or less left (see Section XII)						
Capacity of Tank (gal)	12,000G →					
Substance Stored	REG GAS	PRE GAS				
M/Y Tank installed / Upgraded	05/97 →					
Tank Construction: Bare steel, Sti-P3, Retrofitted sacrificial anode, Impressed Current, Composite, FRP, Interior lining, Vaulted, Double-walled (DW)	DW FRP →					
Spill Prevention	SPILL BUCKETS					
Overfill Prevention (specify type)	BALL FLOAT VALVES					
Special Configuration: Compartmentalized, Manifolded	NO →					

VII. Piping Information

Piping Type: Pressure, Suction	PRESSURE →					
Piping Construction: Bare steel, Sacrificial Anode, Impressed Current, Flex, FRP, Double-walled (DW)	DW FRP →					

Tank and Piping Notes: ✓

VIII. Cathodic Protection

N/A ☑ ✓

Integrity Assessment conducted prior to upgrade							
Interior Lining: Interior lining inspected							
Impressed Current CP Test records							
Rectifier inspection records							
Sacrifical Anode: CP test records	↓	↓					

CP Notes: ✓

Init/Date JKB 05/19/15

NJ0003483

Tank No.	E5	E6				
IX. UST system used solely by Emergency Power Generator	NO →					

X. Release Detection

N/A ☐

Tank RD Methods							
	ATG						
	Interstitial Monitoring	YES →					
	Groundwater Monitoring						
	Vapor Monitoring						
	Inventory Control w/ TTT						
	Manual Tank Gauging						
	Manual Tank Gauging w/ TTT						
	SIR						
12 Months Monitoring Records	*(Must Make Available Last 12 Months For Compliance)*	YES →					

Tank RD Notes: (State What Months Records Were Available, Describe Any Failures and Describe What Investigation Occurred Due to Failure)

I REVIEWED TWELVE PREVIOUS MONTHS OF PASSING ELECTRONIC INTERSTITIAL RESULTS

TANK MONITOR → SIMPLICITY (VEEDER ROOT)

Pressurized Piping RD Methods	N/A ☐					
Interstitial Monitoring						
Groundwater Monitoring						
Vapor Monitoring						
SIR						
12 Months Monitoring Records						
USING ELLA	Annual Line Tightness Test	YES →				
~~ALLD~~	Present	YES →				
	Annual Test	YES →				

Piping RD Notes: (State What Months Records Were Available, Describe Any Failures and Describe What Investigation Occurred Due to Failure)

I REVIEWED PASSING LINE AND LEAK DETECTOR TEST RESULTS

(TEST DATE → 03/25/15)

Init/Date JK 05/15/15

NJ 008 475

XI. Repairs

N/A ☑

Repaired tanks and piping are tightness tested within 30 days of repair completion	Y ☐ N ☐ Unknown ☐
CP systems are tested/inspected within 6 months of repair of any cathodically protected UST system	Y ☐ N ☐ Unknown ☐
Records of repairs are maintained	Y ☐ N ☐ Unknown ☐

XII. Temporary Closure

N/A ☑

CP continues to be maintained	Y ☐ N ☐ Unknown ☐
UST system contains product and release detection is performed	Y ☐ N ☐ Unknown ☐
Cap and secure all lines, pumps, manways	Y ☐ N ☐ Unknown ☐

Notes: ✓

Init/Date JKB 05/19/15

NJ009458

THE UNITED STATES ENVIRONMENTAL PROTECTION AGENCY (EPA) REGION 2 UST PROGRAM
Underground Storage Tank Team
New York, NY 10007-1866

Facility Name SITE # 32094
Address McLEAN BLVD + 33RD ST,
UST Reg # NJ 009458 PATERSON

Inspector Observation Report

Inspection of Underground Storage Tanks (USTs)

☑ No violations observed at the conclusion of this inspection.

☐ The above named facility was inspected by a duly authorized representative of EPA Region 2, and the following are the inspector's observations and/or recommended corrective action(s):

Potential Violations Observed:

Regulatory Citation	Violation Description
§	
§	
§	
§	
§	
§	
§	
§	

Actions Taken:
☐ Field Citation; # _____ ☐ Additional information required ☐ On-site request/Due date _____

Comments/Recommendations:

Name of Owner/Operator Representative:

EDGAR [illegible]
(Please print)

(Signature)

Other Participants: _____

Name of EPA Inspector/representative

JEFFREY K. BLAIR
(Please print)

Jeffrey K Blair
(Signature)

(Credential Number)

Date of Inspection 05/19/15 Time 1:05 AM/PM

Init/Date JKB 05/19/15

NJ0138459

SITE DRAWING

DATE: 05/19/15 TIME ON SITE: 12:40 PM TIME OFF SITE: 1:05 PM

WEATHER: 75° + SUNNY

ENVIRONMENTALLY SENSITIVE AREA : Y☐ N☑
If "Yes", please describe:

GPS AND USTS:

40.96516 'N
-74.06329 'W







PHOTOS

242 FP PRE
243 STP PRE
244 FP REL
245 STP REL
246 FUEL PAD
247 INSIDE DISPENSERS
248 TANK MONITOR
249 SITE

☑Pictures

Init/Date JKB 05/19/15

NN009452

Required Fields to be used for ICIS Only

Compliance Monitoring

Activity: UST Inspection

Inspection Conclusion Data Sheet

1) Did you observe deficiencies (preferred violations) during the on-site inspection? NO

Deficiencies observed: (Put an **X** for each observed deficiency)

___ Potential failure to complete or submit a notification, report, certification, or manifest

___ Potential failure to follow or develop a required management practice or procedure

___ Potential failure to maintain a record or failure to disclose a document

___ Potential failure to maintain/inspect/repair meters, sensors, and recording equipment

___ Potential failure to report regulated events, such as spills, accidents, etc.

2) If you observed deficiencies, did you communicate the deficiencies to the Facility during the inspection? **Yes / No**

3) Did you observe the Facility take any actions during the inspection to address the deficiencies noted? **Yes / No**

If yes, what actions were taken?

4) Did you provide general Compliance Assistance in accordance with the policy on the role of the EPA Inspector In providing Compliance Assistance during Inspections? **(Yes) / No**

5) Did you provide site-specific Compliance Assistance in accordance with the policy on the role of the EPA Inspector in providing Compliance Assistance during the inspection? **(Yes) / No**

Init/Date JH 05/19/15

Release Prevention Compliance Measures Matrix

Regulatory Subject Area	Measure #	SOC Measure / Federal Citation	In Compliance?		
			N/A	Y	N
I. Spill Prevention	1	Spill prevention device is present and functional. [280.20(c)(1)(i), 280.21(d)]		✓	
II. Overfill Prevention	2	Overfill prevention device is present and operational. [280.20(c)(1)(ii), 280.21(d)]		✓	
		☐ Automatic shutoff is operational (ie., device not tampered with or inoperable) [280.20(c)(1)(ii)(A), 280.21(d)] ☐ Alarm is operational. [280.20(c)(1) (ii)(B), 280.21(d)] ☐ Alarm is audible or visible to delivery driver. [280.20(c)(1) (ii)(B), 280.21(d)] ☑ Ball float is operational. [280.20(c)(1)(ii)(B), 280.21(d)]			
III a. Operation and Maintenance	3	Repaired tanks and piping were tightness tested within 30 days of repair completion (not required w/internal inspections or if monthly monitoring is in use). [280.33(d)]	✓		
III b. Operation and Maintenance of Corrosion Protection	4	CP systems were tested/inspected within 6 months of repair of any cathodically protected UST system. [280.33(e)]	✓		
	5	Corrosion protection system is properly operated and maintained to provide continuous protection. [280.31(a)(b), 280.70(a)]	✓		
		☐ UST system (Choose one) ☐ UST in operation ☐ UST in temporary closure ☐ CP System is properly operated and maintained ☐ CP system is performing adequately based on results of testing. [280.31(b)]; - or - ☐ CP system tested within required period and operator is conducting or has completed appropriate repair in response to test results reflecting CP system not providing adequate protection.			

NJ 02 9 45 03

Release Prevention Compliance Measures Matrix

Regulatory Subject Area	Measure #	SOC Measure / Federal Citation	In Compliance?		
			N/A	Y	N
III b. Operation and Maintenance of Corrosion Protection (Continued)	6	UST systems with impressed current cathodic protection are inspected every 60 days. [280.31(c)]	✓		
	7	Lined tanks are inspected periodically and lining is in compliance. [280.21(b)(1)(ii)]	✓		
IV. Tank and Piping Corrosion Protection	8	~~Buried metal tank and piping (which includes fittings, connections, etc.) is corrosion protected.~~ [280.20(a), 280.20(b), 280.21(b), 280.21(c)]		✓	
		☐ Buried metal piping components (such as swing joints, flex-connector, etc.) are isolated from the soil or cathodically protected. For new USTs - tanks and piping installed after 12/22/88 [280.20(a), 280.20(b)]: ☐ Steel tank or piping is coated with suitable dielectric material and cathodically protected. [280.20(a)(2), 280.20(b)(2)] ☑ Tank is fiberglass, clad, or jacketed and piping is fiberglass or flexible plastic. [280.20(a)(1), 280.20(a)(3), 280.20(a)(5), 280.20(b)(1), 280.20(b)(4)] ☐ Records are available to document that CP is not necessary. [280.20(a)(4)(ii), 280.20(b)(3)(ii)] For existing USTs - tanks and piping installed on or before 12/22/88 [280.21(b), 280.21(c)]: ☐ Tank and piping meet new UST requirements [280.21(a)(1)] ☐ Steel tank is internally lined. [280.21 (b)] ☐ Metal tank and piping are cathodically protected. [280.21(b)(2), 280.21(c)]			

Notes: N/A - Indicates that the measure is not applicable.
Any mark in the "N" (No) column means that the facility is not in Significant Operational Compliance (SOC) with Release Prevention Compliance Measures. In order for a compliance measure to be in SOC, all applicable check-box items must be in compliance.

Release Detection Compliance Measures Matrix

Instructions - To Determine Compliance Status of Measures #1-7,
Work Through the Worksheet "Commonly Used Release Detection Methods" Below.

Regulatory Subject Area	Measure #	SOC Measure/ Federal Citation	In Compliance? N/A	Y	N
I. Release Detection Method Presence and Performance Requirements	1	Release detection method is present. [280.40(a)]		✓	
	2	Release detection system is operating properly (i.e., able to detect a release from any portion of the system that routinely contains product). [(280.40(a)(1)]		✓	
	3	Release detection system meets the performance standards at 280.43 or 280.44. [(280.40(a)(3)]		✓	
	4	Implementing agency has been notified of suspected release as required. [(280.40(b)]	✓		
		❑ Non-passing results reported and resolved in accordance with implementing agency's directions. [280.40(b)]			
II. Release Detection Testing	5	Tanks and piping are monitored monthly for releases and records are available (must have records for the two most recent consecutive months and for 8 months of the last 12 months). [280.41(a), and 280.45(b)]		✓	
III. Hazardous Substance UST Systems	6	Hazardous substance UST system leak detection meets the requirements (i.e., either secondarily contained or otherwise approved by the implementing agency). [280.42(b)]	✓		
IV. Temporary Closure	7	Release detection requirements are complied with (i.e., method present, operational, releases investigated and reported as required) for UST systems containing product. [280.70(a)]	✓		

Worksheet - Commonly Used Release Detection Methods

Tank (Choose one)	Pressurized Pipe (Choose Two)	Non-exempt Suction Pipe (Choose one)	Release Detection Method
❑			**A. Inventory Control with Tank Tightness Testing (T.T.T)** ❑ Inventory control is conducted properly. ❑ T.T.T. performed as required (See "D" below). ❑ Inventory volume measurements for inputs, withdrawals, and remaining amounts are recorded each operating day and reconciled as required. [280.43(a)(1), 280.43(a)(3)] ❑ Equipment is capable of 1/8-inch measurement. [280.43(a)(2)] ❑ Product dispensing is metered and recorded within local standards for meter calibration to required accuracy. [280.43(a)(5)] ❑ Water is monitored at least monthly. [280.43(a)(6)]

NV 0000459

Worksheet (Continued) - Commonly Used Release Detection Methods

Tank (Choose one)	Pressurized Pipe (Choose Two)	Non-exempt Suction Pipe (Choose one)	Release Detection Method
☐			**B. Automatic Tank Gauge (ATG)** ☐ ATG is set up properly. [280.40(a)(2)] ☐ ATG can detect a 0.2 gal/hr leak rate from any portion of the tank routinely containing product. [280.43(d)(1)] ☐ ATG is checking portion of tank that routinely contains product. [280.40(a)(1)]
☐			**C. Manual Tank Gauging (MTG)** ☐ Tank size is appropriate for using MTG. [280.43(b)(5)] ☐ Tanks 1001 gals (as per EPA memo) and greater restricted to use with T.T.T. (See "D" below) ☐ Method is being conducted correctly. [280.43(b)(4)] ☐ No liquid was added to or taken out of the tank during the test. [280.43(b)(1)] ☐ Equipment is capable of 1/8-inch measurement. [280.43(b)(3)]
☐	☑	☐	**D. Tightness Testing** (Safe Suction piping does not require testing) ☐ Testing method is capable of detecting a 0.1 gal/hr leak rate from any portion of tank routinely containing product. [280.43(c)] ☑ Tightness testing is conducted within specified time frames for method: ☐ **Tanks** - every 5 years [280.41(a)(1)] ☑ **Pressurized Piping** - annually [280.41(b)(1)(ii)] ☐ **Non-exempt suction piping** - every 3 years [280.41(b)(2)] ☐ Tightness testing is conducted following manufacturer's instructions. [280.40(a)(3)]
☐	☐	☐	**E. Ground Water or Vapor Monitoring** ☐ Ground water in the monitoring well is never more than 20 feet from the ground surface. [280.43(f)(2)] ☐ Vapor monitoring well is not affected by high ground water. [280.43(e)(3)] ☐ Site assessment has been done for vapor or ground water monitoring. [280.43(e)(6), 280.43(f)(7)] ☐ Wells are properly designed and positioned. [280.43(e)(6), 280.43(f)(7)]
☑	☐	☐	**F. Interstitial Monitoring** ☑ Secondary containment can be used to detect a release [280.43(g)(1)], 280.43(g)(2)] ☐ Sensor properly positioned. [280.40(a)(2)]

NJ0039475

Release Detection Compliance Measures Matrix

Worksheet (Continued) - Commonly Used Release Detection Methods			
Tank (Choose one)	**Pressurized Pipe** (Choose Two)	**Non-exempt Suction Pipe** (Choose one)	**Release Detection Method**
	☑		**G. Automatic Line Leak Detector (ALLD)** ELLD ☑ ALLD is present and operational. [280.44(a)] ☑ Annual function test of the ALLD has been conducted and records are available. [280.44(a)]
☐	☐	☐	**H. Other Methods [e.g., Statistical Inventory Reconciliation (S.I.R.)]** ☐ The method can detect a 0.2 gal/hr leak rate or a release of 150 gal within a month and meet the 95/5 requirement [280.43(h)(1)]; or ☐ The implementing agency has approved the method as being as effective as tank tightness testing, automatic tank gauging, vapor monitoring, ground water monitoring, or interstitial monitoring and the operator complies with any conditions imposed by agency. [280.43(h)(2)] ☐ S.I.R. - Results are received within time frame established by implementing agency. [280.41(a) & 280.43(h)]

Notes: N/A - Indicates that the measure is not applicable.

Any mark in the "N" (No) column means that the facility is not in Significant Operational Compliance (SOC) with Release Detection Compliance Measures.

In order for a compliance measure to be in SOC, all applicable check-box items must be in compliance.









246 NJ 0118454 247

United States Environmental Protection Agency (EPA)
Region 2
290 Broadway
New York, NY 10007-1866

Underground Storage Tank (UST) Inspection Form

INSPECTOR NAME(S): JEFF BLAIR **DATE:** 10/05/12

SIC CODE: **ICIS #:**

I. Location of Tank(s) ☐ Tribal

Facility Name: NJ ENERGY CORP # 32034
Street Address: 19 EAST 33RD STREET
City: PATERSON State: NJ Zip Code: 07514
County: PASSAIC
Phone Number: (973) 278-3966 Fax Number:
Contact Person(s): EDGAR AMADOR, ENV. COMP. SPECIALIST

II. Ownership of Tank(s) ☐ same as location (I.)

Owner Name: NJ ENERGY CORP.
Street Address: 536 MAIN STREET
City: NEW PALTZ State: NY Zip Code: 12561
County:
Phone Number: (845) 256-0162 Fax Number:
Contact Person(s): SCOTT PARKER, DIRECTOR-FACILITIES

IIA. Ownership of Other Facilities

☐Do you own other UST Facilities (Yes) / No

If Yes, How many Facilities 34 How many USTs 112

III. Notification

☐ Notification to implementing agency; name NJ DEP (EFFECTIVE THROUGH 03/31/14)
State Facility ID # 008458

IV. Financial Responsibility CHARTIS SPECIALTY INSURANCE CO.

☐ State Fund ☐ Private Insurance: Insurer/Policy # ST 584-4288
☐ Guarantee ☐ Surety Bond ☐ Letter of Credit
☐ Local Government ☐ Self Insured ☐ **Not Required** (Federal & State government, hazardous substance USTs)

V. Release History N/A ☐

☐ To your knowledge, are there any public or private Drinking Water Wells in the vicinity ? **Yes / No**

☐ Evidence of release or spills at facility ☐ Greater than 25 gallons (estimate)
☐ **Releases reported to implementing agency; if so, date(s)** _____ [280.53]
☐ Release confirmed; when and how _____
☐ Initial abatement measures and site characterization ☐ Free product removal
☐ Soil or ground water contamination ☐ Corrective action plan submitted
☑ Remediation ongoing ☐ Remediation completed, no further action; date(s) _____

Notes: ENVIRONMENTAL CONTACT → KLEINFELDER EAST, INC. (800) 353-0052

VI. Tank Information	Tank No.	E5	E6				
Tank presently in use		YES →					
If not, date last used	(see Section XII)						
If empty, verify 1" or less left	(see Section XII)						
Capacity of Tank (gal)		12,000 G →					
Substance Stored		GASOLINE →					
M/Y Tank installed / Upgraded		05/97 →					
Tank Construction: Bare steel, Sti-P3, Retrofitted sacrificial anode, Impressed Current, Composite, FRP, Interior lining, Vaulted, Double-walled (DW)		DW FRP →					
Spill Prevention		SPILL BUCKETS →					
Overfill Prevention (specify type)		BALL FLOAT VALVES					
Special Configuration: Compartmentalized, Manifolded		NO →					

VII. Piping Information							
Piping Type: Pressure, Suction		PRESSURE →					
Piping Construction: Bare steel, Sacrificial Anode, Impressed Current, Flex, FRP, Double-walled (DW)		DW FRP →					

Tank and Piping Notes: ✓

VIII. Cathodic Protection		N/A ☑ ✓					
Integrity Assessment conducted prior to upgrade							
Interior Lining:	Interior lining inspected						
Impressed Current	CP Test records						
	Rectifier inspection records						
Sacrifical Anode:	CP test records	↓	↓				

CP Notes: ✓

Tank No.	E5	E6				
IX. UST system used solely by Emergency Power Generator	No →					

X. Release Detection

N/A ☐

Tank RD Methods							
	ATG						
	Interstitial Monitoring	YES →					
	Groundwater Monitoring						
	Vapor Monitoring						
	Inventory Control w/ TTT						
	Manual Tank Gauging						
	Manual Tank Gauging w/ TTT						
	SIR						
12 Months Monitoring Records (*Must* Make Available Last 12 Months For Compliance)		NO →					

Tank RD Notes: (State What Months Records Were Available, Describe Any Failures and Describe What Investigation Occurred Due to Failure)

I REVIEWED 3/12 PREVIOUS MONTHS OF PLEWE ELECTRONIC INTERSTITIAL RESULTS

JULY → SEP 2012 ONLY

TANK MONITOR → SIMPLICITY

Pressurized Piping RD Methods		N/A ☐					
	Interstitial Monitoring						
	Groundwater Monitoring						
	Vapor Monitoring						
	SIR						
12 Months Monitoring Records							
	Annual Line Tightness Test	YES →					
ALLD	Present	YES →					
	Annual Test	YES →					

Piping RD Notes: (State What Months Records Were Available, Describe Any Failures and Describe What Investigation Occurred Due to Failure)

I REVIEWED PASSING LEAK DETECTOR AND PRESSURIZED LINE TEST RESULTS

TEST DATE → 04/19/12

Init/Date JKB 10/05/12

XI. Repairs

N/A ☑

Repaired tanks and piping are tightness tested within 30 days of repair completion	Y ☐ N ☐ Unknown ☐
CP systems are tested/inspected within 6 months of repair of any cathodically protected UST system	Y ☐ N ☐ Unknown ☐
Records of repairs are maintained	Y ☐ N ☐ Unknown ☐

XII. Temporary Closure

N/A ☐

CP continues to be maintained	Y ☐ N ☐ Unknown ☐
UST system contains product and release detection is performed	Y ☐ N ☐ Unknown ☐
Cap and secure all lines, pumps, manways	Y ☐ N ☐ Unknown ☐

Notes:

THE UNITED STATES ENVIRONMENTAL PROTECTION AGENCY (EPA) REGION 2 UST PROGRAM
Ground Water Compliance Section
New York, NY 10007-1866

Inspector Observation Report

Inspection of Underground Storage Tanks (USTs)

☐ No violations observed at the conclusion of this inspection.

☐ The above named facility was inspected by a duly authorized representative of EPA Region 2, and the following are the inspector's observations and/or recommended corrective action(s):

Violations Observed:

Regulatory Citation	Violation Description
§ 280.45	FAILURE TO MAINTAIN RECORDS OF RELEASE DETECTION
§	MONITORING
§	
§	
§	
§	
§	
§	

Actions Taken:
☐ Field Citation; # _____ ☐ Additional information required ☐ On-site request/Due date _____

Comments/Recommendations:
PROVIDED ONLY 3/12 PREVIOUS MONTHS OF TANK RELEASE DETECTION RESULTS

Name of Owner/Operator Representative:
Edgar Amador (Please print)
(Signature)

Other Participants: _____

Name of EPA Inspector/representative
JEFFREY K BLAIR (Please print)
Jeffrey K Blair (Signature)
(Credential Number)

Date of Inspection 10/05/12 Time 11:10 AM/PM

Init/Date JKB 10/05/12

SITE DRAWING

DATE: 10/05/12 TIME ON SITE: 1513 PM TIME OFF SITE: 11:10 AM

WEATHER: 85° & SUNNY

ENVIRONMENTALLY SENSITIVE AREA : Y ☐ N ☑
If "Yes", please describe:







PHOTOS

129 FP
130 STP
131 FP
132 STP
133 FUEL PAD
134 TANK MONITOR
135 SPILL SIGN
136 SITE

☑ Pictures

Init/Date JKB 10/05/12

2003453

Required Fields to be used for ICIS Only

Compliance Monitoring

Activity: UST Inspection

Inspection Conclusion Data Sheet

1) Did you observe deficiencies (preferred violations) during the on-site inspection? Yes

Deficiencies observed: (Put an **X** for each observed deficiency)

X Potential failure to complete or submit a notification, report, certification, or manifest

X Potential failure to follow or develop a required management practice or procedure

X Potential failure to maintain a record or failure to disclose a document

X Potential failure to maintain/inspect/repair meters, sensors, and recording equipment

___ Potential failure to report regulated events, such as spills, accidents, etc.

2) If you observed deficiencies, did you communicate the deficiencies to the Facility during the inspection? **(Yes) / No**

3) Did you observe the Facility take any actions during the inspection to address the deficiencies noted? **Yes / No**

If yes, what actions were taken? (3) WILL RESEARCH AND FORWARD MISSING TANK MONITORING RESULTS

4) Did you provide general Compliance Assistance in accordance with the policy on the role of the EPA Inspector In providing Compliance Assistance during Inspections? **(Yes) / No**

5) Did you provide site-specific Compliance Assistance in accordance with the policy on the role of the EPA Inspector in providing Compliance Assistance during the inspection? **(Yes) / No**

Init/Date JKB 10/05/12

Release Prevention Compliance Measures Matrix

Regulatory Subject Area	Measure #	SOC Measure / Federal Citation	In Compliance?		
			N/A	Y	N
I. Spill Prevention	1	Spill prevention device is present and functional. [280.20(c)(1)(i), 280.21(d)]		✓	
II. Overfill Prevention	2	Overfill prevention device is present and operational. [280.20(c)(1)(ii), 280.21(d)]		✓	
		☐ Automatic shutoff is operational (ie., device not tampered with or inoperable) [280.20(c)(1)(ii)(A), 280.21(d)]			
		☐ Alarm is operational. [280.20(c)(1) (ii)(B), 280.21(d)]			
		☐ Alarm is audible or visible to delivery driver. [280.20(c)(1) (ii)(B), 280.21(d)]			
		☑ Ball float is operational. [280.20(c)(1)(ii)(B), 280.21(d)]			
III a. Operation and Maintenance	3	Repaired tanks and piping were tightness tested within 30 days of repair completion (not required w/internal inspections or if monthly monitoring is in use). [280.33(d)]	✓		
III b. Operation and Maintenance of Corrosion Protection	4	CP systems were tested/inspected within 6 months of repair of any cathodically protected UST system. [280.33(e)]	✓		
	5	Corrosion protection system is properly operated and maintained to provide continuous protection. [280.31(a)(b), 280.70(a)]	✓		
		☐ UST system (Choose one)			
		☐ UST in operation			
		☐ UST in temporary closure			
		☐ CP System is properly operated and maintained			
		☐ CP system is performing adequately based on results of testing. [280.31(b)]; - or -			
		☐ CP system tested within required period and operator is conducting or has completed appropriate repair in response to test results reflecting CP system not providing adequate protection.			

Release Prevention Compliance Measures Matrix

Regulatory Subject Area	Measure #	SOC Measure / Federal Citation	In Compliance?		
			N/A	Y	N
III b. Operation and Maintenance of Corrosion Protection (Continued)	6	UST systems with impressed current cathodic protection are inspected every 60 days. [280.31(c)]	✓		
	7	Lined tanks are inspected periodically and lining is in compliance. [280.21(b)(1)(ii)]	✓		
IV. Tank and Piping Corrosion Protection	8	~~Buried metal tank and piping (which includes fittings, connections, etc.) is corrosion protected.~~ [280.20(a), 280.20(b), 280.21(b), 280.21(c)]		✓	
		☐ Buried metal piping components (such as swing joints, flex-connector, etc.) are isolated from the soil or cathodically protected. For new USTs - tanks and piping installed after 12/22/88 [280.20(a), 280.20(b)]: ☐ Steel tank or piping is coated with suitable dielectric material and cathodically protected. [280.20(a)(2), 280.20(b)(2)] ☑ Tank is fiberglass, clad, or jacketed and piping is fiberglass or flexible plastic. [280.20(a)(1), 280.20(a)(3), 280.20(a)(5), 280.20(b)(1), 280.20(b)(4)] ☐ Records are available to document that CP is not necessary. [280.20(a)(4)(ii), 280.20(b)(3)(ii)] For existing USTs - tanks and piping installed on or before 12/22/88 [280.21(b), 280.21(c)]: ☐ Tank and piping meet new UST requirements [280.21(a)(1)] ☐ Steel tank is internally lined. [280.21 (b)] ☐ Metal tank and piping are cathodically protected. [280.21(b)(2), 280.21(c)]			

Notes: N/A - Indicates that the measure is not applicable.
Any mark in the "N" (No) column means that the facility is not in Significant Operational Compliance (SOC) with Release Prevention Compliance Measures. In order for a compliance measure to be in SOC, all applicable check-box items must be in compliance.

Release Detection Compliance Measures Matrix

Instructions - To Determine Compliance Status of Measures #1-7,
Work Through the Worksheet "Commonly Used Release Detection Methods" Below.

Regulatory Subject Area	Measure #	SOC Measure/ Federal Citation	In Compliance? N/A	Y	N
I. Release Detection Method Presence and Performance Requirements	1	Release detection method is present. [280.40(a)]		✓	
	2	Release detection system is operating properly (i.e., able to detect a release from any portion of the system that routinely contains product). [(280.40(a)(1)]		✓	
	3	Release detection system meets the performance standards at 280.43 or 280.44. [(280.40(a)(3)]		✓	
	4	Implementing agency has been notified of suspected release as required. [(280.40(b)]	✓		
		☐ Non-passing results reported and resolved in accordance with implementing agency's directions. [280.40(b)]			
II. Release Detection Testing	5	Tanks and piping are monitored monthly for releases and records are available (must have records for the two most recent consecutive months and for 8 months of the last 12 months). [280.41(a), and 280.45(b)]			✓
III. Hazardous Substance UST Systems	6	Hazardous substance UST system leak detection meets the requirements (i.e., either secondarily contained or otherwise approved by the implementing agency). [280.42(b)]	✓		
IV. Temporary Closure	7	Release detection requirements are complied with (i.e., method present, operational, releases investigated and reported as required) for UST systems containing product. [280.70(a)]	✓		

Worksheet - Commonly Used Release Detection Methods

Tank (Choose one)	Pressurized Pipe (Choose Two)	Non-exempt Suction Pipe (Choose one)	Release Detection Method
☐			**A. Inventory Control with Tank Tightness Testing (T.T.T)** ☐ Inventory control is conducted properly. ☐ T.T.T. performed as required (See "D" below). ☐ Inventory volume measurements for inputs, withdrawals, and remaining amounts are recorded each operating day and reconciled as required. [280.43(a)(1), 280.43(a)(3)] ☐ Equipment is capable of 1/8-inch measurement. [280.43(a)(2)] ☐ Product dispensing is metered and recorded within local standards for meter calibration to required accuracy. [280.43(a)(5)] ☐ Water is monitored at least monthly. [280.43(a)(6)]

Worksheet (Continued) - Commonly Used Release Detection Methods

Tank (Choose one)	Pressurized Pipe (Choose Two)	Non-exempt Suction Pipe (Choose one)	Release Detection Method
☐			**B. Automatic Tank Gauge (ATG)** ☐ ~~ATG is set up properly. [280.40(a)(2)]~~ ☐ ATG can detect a 0.2 gal/hr leak rate from any portion of the tank routinely containing product. [280.43(d)(1)] ☐ ATG is checking portion of tank that routinely contains product. [280.40(a)(1)]
☐			**C. Manual Tank Gauging (MTG)** ☐ Tank size is appropriate for using MTG. [280.43(b)(5)] ☐ Tanks 1001 gals (as per EPA memo) and greater restricted to use with T.T.T. (See "D" below) ☐ Method is being conducted correctly. [280.43(b)(4)] ☐ No liquid was added to or taken out of the tank during the test. [280.43(b)(1)] ☐ Equipment is capable of 1/8-inch measurement. [280.43(b)(3)]
☐	☑	☐	**D. Tightness Testing** (Safe Suction piping does not require testing) ☐ Testing method is capable of detecting a 0.1 gal/hr leak rate from any portion of tank routinely containing product. [280.43(c)] ☑ Tightness testing is conducted within specified time frames for method: ☐ **Tanks** - every 5 years [280.41(a)(1)] ☑ **Pressurized Piping** - annually [280.41(b)(1)(ii)] ☐ **Non-exempt suction piping** - every 3 years [280.41(b)(2)] ☐ Tightness testing is conducted following manufacturer's instructions. [280.40(a)(3)]
☐	☐	☐	**E. Ground Water or Vapor Monitoring** ☐ Ground water in the monitoring well is never more than 20 feet from the ground surface. [280.43(f)(2)] ☐ Vapor monitoring well is not affected by high ground water. [280.43(e)(3)] ☐ Site assessment has been done for vapor or ground water monitoring. [280.43(e)(6), 280.43(f)(7)] ☐ Wells are properly designed and positioned. [280.43(e)(6), 280.43(f)(7)]
☐	☐	☐	**F. Interstitial Monitoring** ☑ Secondary containment can be used to detect a release [280.43(g)(1)], 280.43(g)(2)] ☐ Sensor properly positioned. [280.40(a)(2)]

Worksheet (Continued) - Commonly Used Release Detection Methods

Tank (Choose one)	Pressurized Pipe (Choose Two)	Non-exempt Suction Pipe (Choose one)	Release Detection Method
	☑		**G. Automatic Line Leak Detector (ALLD)** ☐ ALLD is present and operational. [280.44(a)] ☑ Annual function test of the ALLD has been conducted and records are available. [280.44(a)]
☐	☐	☐	**H. Other Methods [e.g., Statistical Inventory Reconciliation (S.I.R.)]** ☐ The method can detect a 0.2 gal/hr leak rate or a release of 150 gal within a month and meet the 95/5 requirement [280.43(h)(1)]; or ☐ The implementing agency has approved the method as being as effective as tank tightness testing, automatic tank gauging, vapor monitoring, ground water monitoring, or interstitial monitoring and the operator complies with any conditions imposed by agency. [280.43(h)(2)] ☐ S.I.R. - Results are received within time frame established by implementing agency. [280.41(a) & 280.43(h)]

Notes: N/A - Indicates that the measure is not applicable.

Any mark in the "N" (No) column means that the facility is not in Significant Operational Compliance (SOC) with Release Detection Compliance Measures.

In order for a compliance measure to be in SOC, all applicable check-box items must be in compliance.


2012.10.05 10:43


2012.10.05 10:44


2012.10.05 10:43


2012.10.05 10:43

008458


SIMPLICITY
Property of VEEDER-ROOT
ALARM
WARNING
POWER
ALL FUNCTIONS NORMAL
2012.10.05 10:52


2012.10.05 11:10




Environmental Investigation/
Cleanup In Progress At This Site
For Further Information Contact:
Kleinfelder East, Inc.,
On Behalf of the New Jersey Energy
Realty, LLC.
(800) 353-0052
SRPID# 008458
Posted On 7/10/12
2012.10.05 10:56